

01 APR 16 AM 9:10

126401

March, 23 2001

Federal Aviation Administration  
Office of Chief Counsel  
800 Independence Ave, SW.  
Washington, DC 20591  
Attention: Rules Docket, AGC-10

FAA-01-9438-1

Ida M. Klepper;

Please submit to Aberdeen Flying Service an exemption to the FAR 135.143© in accordance with (Exemption No. 6875). For reasons; #1 The expense of changing our fleet of aircraft over to this new system that has not been proven to be reliable will have to be passed on to public. #2 the current system has been in affect for many years and has proven to be adequate. The new system will not adversely effect public safety in its advantage and reliability over the old system.

Thanks,



Daryl

Director of Maintenance  
Aberdeen Flying Service  
4430 East Hwy 12  
Aberdeen, SD 57401